

**MONTGOMERY ROAD**

Scale: 1:750

● Replant Location ● Existing Tree for Removal

© Crown copyright and database rights 2016 Ordnance Survey 100018816





**MONTGOMERY ROAD**


Scale: 1:750

● Replant Location    ● Existing Tree for Removal

© Crown copyright and database rights 2016 Ordnance Survey 100018816







**MONTGOMERY ROAD**

Scale: 1:2,000



● Replant Location    ● Existing Tree for Removal

© Crown copyright and database rights 2016 Ordnance Survey 100018816

Original Tree Position	Site	Original Tree Species	Confirm Reason for Removal	6 D's	Original Tree Easting	Original Tree Northing	Planting Notes	Replant Species	Replant Easting	Replant Northing
o/s 90	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434185.61	385020.41	TR: Replanting, Tilia 'Rancho' - Plant in verge centrally o/s 90 (same as felled tree)	Tilia cordata 'Rancho'	434185.67	385020.52
o/s 92-94, between the two	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434175.44	385009.56	TR: Replanting, Tilia 'Rancho' - Plant in verge between 92-94 (same as felled tree)	Tilia cordata 'Rancho'	434175.94	385009.7
o/s 76	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434245.18	385085.58	TR: Replanting, Tilia 'Rancho' - Plant in verge centrally o/s 76 (same as felled tree)	Tilia cordata 'Rancho'	434245.26	385085.42
o/s 9, opposite 12	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434487.47	385338.46	TR: Replanting, Tilia 'Rancho' - Plant in new pit o/s 9/OPPOSITE 12 (same as felled tree)	Tilia cordata 'Rancho'	434487.41	385338.37
o/s 99-101, next to driveway	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434164.85	384984.81	TR: Replanting, Tilia 'Rancho' - Plant in verge adj 99 driveway (same as felled tree)	Tilia cordata 'Rancho'	434164.68	384984.57

o/s 102	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434149.25	384980.32	TR: Replanting, Tilia 'Rancho' - Plant in verge o/s 102 (same as felled tree)	Tilia cordata 'Rancho'	434149.77	384981.73
o/s 29	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434394.16	385236.56	TR: Replanting, Tilia 'Rancho' - Plant in new pit o/s 29 (same as felled tree)	Tilia cordata 'Rancho'	434393.34	385234.14
o/s 72	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434261.79	385103.46	TR: Replanting, Tilia 'Rancho' - Plant in verge centrally o/s 70-72 (relocated slightly to between 2 properties)	Tilia cordata 'Rancho'	434267.94	385110.03
o/s 28	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434421.53	385279.19	TR: Replanting, Tilia 'Rancho' - Plant in new pit o/s 28 (same as felled tree)	Tilia cordata 'Rancho'	434421.57	385278.74
o/s 74	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434254.17	385095.83	TR: Replanting, Tilia 'Rancho' - Plant in verge centrally o/s 74 (same as felled tree)	Tilia cordata 'Rancho'	434254.67	385095.92

o/s 22	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434438.48	385297.58	TR: Replanting, Tilia 'Rancho' - Plant in new pit o/s 22 (same as felled tree)	Tilia cordata 'Rancho'	434438.72	385297.73
o/s 88	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434193.57	385029.14	TR: Replanting, Tilia 'Rancho' - Plant in verge centrally o/s 84-86 (relocated slightly to clear from driveways)	Tilia cordata 'Rancho'	434200.38	385037.77
o/s 6b and 6c	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434507.13	385373.88	TR: Replanting, Tilia 'Rancho' - Plant in new pit o/s between 6c-4 (same as felled tree)	Tilia cordata 'Rancho'	434508.78	385375.31
o/s 97	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434182.56	385003.97	TR: Replanting, Tilia 'Rancho' - Plant in verge o/s 97 (same as felled tree)	Tilia cordata 'Rancho'	434182.65	385003.75
o/s 78	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434235.35	385075.41	TR: Replanting, Tilia 'Rancho' - Plant in verge centrally o/s 78 (same as felled tree)	Tilia cordata 'Rancho'	434236.57	385076.37

o/s 96	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434166.37	384999.31	TR: Replanting, Tilia 'Rancho' - Plant in verge o/s 96 centrally (same as felled tree)	Tilia cordata 'Rancho'	434162.34	384997.64
o/s 82	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434220.21	385059.16	TR: Replanting, Tilia 'Rancho' - Plant in verge o/s 82 (same as felled tree)	Tilia cordata 'Rancho'	434220.89	385059.24
o/s 80-82	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434227.98	385066.42	TR: Replanting, Tilia 'Rancho' - Plant in verge o/s 80 (same as felled tree)	Tilia cordata 'Rancho'	434226.8	385065.64
o/s 14-16 (toward 14)	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434471.62	385334.05	TR: Replanting, Tilia 'Rancho' - Plant in new pit o/s 14 (same as felled tree)	Tilia cordata 'Rancho'	434472.1	385334.81
o/s 13-15	MONTGOMERY ROAD	Tilia x europea	Damage to Surface	Damaging	434461.61	385310.46	TR: Replanting, Tilia 'Rancho' - Plant in new pit o/s 13-15 (same as felled tree)	Tilia cordata 'Rancho'	434461.55	385310.4